

Dart Aerospace Ltd

W/O:		WORK ORDER CHA	NGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
				·			
		·					
Part No	:	PAR #: Fault Category:	NCR: Ye	s No DQ	A:	Date: _	
			QA:	N/C Close	d:	_ Date: _	

NCR: WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B			Approval	Ammanual
DATE	STEP	STEP Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Chief Eng	Approval QC Inspector
		•						

Date:

Thursday, 4/12/2007 8:53:03 AM

User:

Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: RH ACTUATOR ASSEBLY

Job Number: 31746

Part Number: 41232 200 001 002

Job Number:



Seq. #:

Machine Or Operation:

Description:

20.0

QC21

FINAL INSPECTION/W/O RELEASE







Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



Dart Ae	rospace	Ltd							
W/O:			V	VORK ORDER CHANGE	ES	* M			
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						<u></u>			
Part No):	PAR #:	Fault Ca	tegory:	NCR: Yes	No) DQ	A:	$\underline{\mathcal{V}}$ Date: $\underline{\mathcal{C}}$	37105/15
					QA: N	V/C Close	d:	Date: _	
NCR:		,	WORK OR	DER NON-CONFORMA	NCE (NC	₹)			
		Description of NC		Corrective Action Section	n B	Verifi	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Section C		Chief Eng	QC Inspector
	1		1 1						

NCR:	į	WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC	Corrective Action Section B		Verification	A				
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector		
								:		

	Process Sheet	OTHATOD ACCEDING	
Customer: CU-DAR001 Dart Helicopters Services	Drawing Name: RH A	CTUATOR ASSEBLY	
Job Number: 31746	Part Number: 4123	2 200 001 002	
ob Number:			
Seq. #: Machine Or Operation:	Descripti	on:	
13.0 41232 200 002 005	pivot arm	11101111011111	
Comment: Qty.: 1.0000 Each(s)/Unit Tota	I: 4.0000 Each(s)	111111111111111111111111111111111111111	
pivot arm			()
Buton.	latah		
14.0. 41232 200 002 003	latch		
Comment: Qty.: 1.0000 Each(s)/Unit Tota	I: 4.0000 Each(s)		
latch Batch: B31777		CA	62/-115
Batch: 13 3 1 7 7 7 15.0 41232 200 002 001	tube	<u> </u>	0.7/25/13
11000 1			
Comment: Qty.: 1.0000 Each(s)/Unit Total	I: 4.0000 Each(s)		
tube		SB	07/05/15
16.0 41232 200 008 001	Decal		0 7 103/18
Comment: Qty.: 1.0000 Each(s)/Unit Total	I : 4.0000 Each(s)		
Decal	•	.	2/-1/-
数 Batch: <u>M ろしい</u> ろ 17.0 SMALL FAB 1	SMALL & MEDIUM FAB RESOURCE	S/B	07/05/15
17.0 SMALL PAB I	SIMALE & MILDION 1 AD NESCONCE		
Comment: SMALL & MEDIUM FAB RESOURC			
1- Assemble as per Dwg 41232-200-	001		
2-Torque as per Dwg 41232-200-001		SB	07/05/15
18.0 QC5	INSPECT WORK TO CURRENT STEI		
	// / / / / / / / / / / / / / / / / / / /	3	
Comment: INSPECT WORK TO CURRENT ST	FP FP		
19.0 PACKAGING 1	PACKAGING RESOURCE #1		
Comment: PACKAGING RESOURCE #1			
Identify and Stock			
Location:	07/8/17 (<i>ſ</i>	<u>-</u>

Form: rorocess


Page 3

Dart	Aerospace	Ltd

W/O:		WORK ORDER CHANGES								
DATE	STEP	TEP PROCEDURE CHANGE			Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
०२१०५।ऽ		2 Spring 51455 Batch MP4079 Put E Rogon Batch M104251 on spring	SB	87/25/15	- 3	67.07.17	6265-17			

Part No: _	 PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
			QA: N/C	losed:	Date:

NCR: WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B			A	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector
·								
	,							
	·							
		•						



Dart Aerospace Lt

W/O:		WORK ORDER CH	ANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
salust 11	ц.	split wo	813	07/05/11	73		
Part No	o:	PAR #: Fault Category:	NCR: Yes	No DQA	۸:	Date: _	

QA: N/C Closed: _____ Date: ____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B	}	Verification	Approval Chief Eng	Approval QC Inspector		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C				

	ursday, 4/12/2007 8:53:03 A	M				Sp	THE STATE OF THE S	07/05/4
	n Johnston		Proce	ess Sheet			<u> 83</u>	0710510
Customer Job Number Estimate Numbe	: 31746	art Helicopters Service	es	Drawing Name	: RH ACTUATO	OR ASSEBLY		
P.O. Number This Issue Prsht Rev.	: NIA	S.O. No. : 1 1		Part Number Drawing Number Project Number	: 41232 200 00 : 41232-200-00 : N/A		`	\
First Issue Previous Run	4 3/ A	Type : SMALL/	MED FAB	Drawing Revision Material Due Date	: IR : µ A : 5/10/2007	Qty:	4 U	m: Each
Written By Checked & Appro	: oved By : : Est Re	ev:A New Issue 07-0	4.12 2-28 JLM	- ·	. 3/10/2001	uty.	4 0	III. Luon
Additional Produ	ict					-		
Job Number:								
Seq. #:	Machine Or Op	eration:		Description :				
1.0	MS208224		elbow	•	***			
Com	nent: Qty.: 1.000 elbow X	0 Each(s)/Unit To	otal : 4.0000 Ea	ach(s) tock	<u>~</u>)		_	
	Batch: M	103 C38	(2) H	104427	ν		SK	07/05/15
2.0	124K002 4CR 0545		Hose ass	'y-Step Actuator				-
7 N	Hose ass'y-Ste BATCH:	, ,	otal : 4.0000 Ea	art I pech	y kit	u	<u> </u>	1
3.0	AN8424D		Elbow)		(
Comi	Elbow	0 Each(s)/Unit To	otal : 4.0000 Ea	ach(s)		SB	07/	05/15
4.0	41232 200 007 001		Brass Cy	linder Assembly				
Comr	ment: Qty.: 1.000 Brass Cylinder Batch:人	0 Each(s)/Unit To Assembly ひ ろっタリン	otal: 4.0000 Ea	ach(s)	. Left ove	n(3)	·	;
5.0	41232 200 003 001			tep Actuator)		,		
₹V Comr	nent: Qty.: 1.000 Spring (Step A Batch:	` '	otal: 4.0000 Ea	ach(s)	list	11	1	
			7					